00862.021692.

e Patent of:

PATENT PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

AOJI ISONO ET AL.

Art Unit: 2673

Examiner: P.M. Dharia

Appln. No.: 09/719,523

Filed: October 5, 1999

For: METHOD OF CONTROLLING

IMAGE DISPLAY

U.S. Patent No.: 6,972,741 B1

Issued: December 6, 2005 : July 26, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION 7/2005 SOCIMON MARKETS 5972741

UNDER RULES 322 AND 323

UNDER RULES 322 AND 323

100.00 (P)

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank DeLucia

Attorney for Patentees

Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 570560v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents:

"3055738 3/1991" should read --3-055738 3/1991--;

"4028137 1/1992" should read --4-028137 1/1992--;

"2257551 10/1990" should read 2-257551 10/1990--;

"1031332 2/1989" should read --1-031332 2/1989--;

"03048889 1/1991" should read --03-048889 1/1991--;

"04204993A 7/1992" should read --04-204993A 7/1992--;

"02273720 8/1990" should read --02-273720 8/1990--;

"02272490 7/1990" should read --02-272490 7/1990--:

"0 707 301 A1 4/1976" should read --0 707 301 A1 4/1996--; and

Other Publications after ""Physical":

"Emisssion" should read -- Emission -- and

"Molybedium" should read --Molybdenum--.

SHEET 5:

Figure 5, "LIMINANCE" should read -- LUMINANCE--.

SHEET 6:

Figure 6, "REGURATOR" should read --REGULATOR-- and "RAGURATOR" should read --REGULATOR--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 570560v1 PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

 \Rightarrow ____

JUI 31 ZUU6

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 7:

Figure 7, REGURATOR" should read --REGULATOR-- and "RAGURATOR" should read --REGULATOR--.

COLUMN 1:

Line 2, "DISPLAY" should read -- DISPLAY ¶TECHNICAL FIELD--.

COLUMN 2:

Line 8, "denium" should read --denum--.

COLUMN 3:

Line 12, "Microele-ctronics" should read -- Microelectronics--.

COLUMN 4:

Line 21, "3kv" should read --3kV--.

COLUMN 6:

Line 57, "while" should read --while an image--.

COLUMN 15:

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) NY Main 570560v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "step s47." should read --step S47.--.

COLUMN 28:

Line 54, "show" should read --shows--.

COLUMN 33:

Line 9, "take" should read --taken--.

COLUMN 34:

Line 1, "for" should read --that--;

Line 19, "character graphic" should read --character-graphic--; and

Line 22, "character graphic" should read --character-graphic--.

COLUMN 36:

Line 37, "source; an" should read --source; ¶ an--; and

Line 65, "source; an" should read --source; ¶ an--.

COLUMN 37:

Line 18, "comprising" should read --comprises--;

Line 27, "source; an" should read --source; ¶ an--;

Line 47, "comprising" should read --comprises--; and

Line 51, "connect" should read --connected--.

Line 56, "source; an" should read --source; ¶ an--;

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY Main 570560v1

PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 14, "shutdown" should read --shutdown,--;

Line 19, "comprising" should read --comprises--;

Line 28, "source; an" should read --source; ¶ an--;

Line 41, "battery;" should read --battery; and--; and

Line 50, "source-comprising" should read --source comprises--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

(212) 218-2200 - 1 Form PTO 1050 (Rev. 3-82)

NY_Main 570560v1

PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page



Stable Ould Here STAIN I'RE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents:

"3055738 3/1991" should read --3-055738 3/1991--;

"4028137 1/1992" should read --4-028137 1/1992--;

"2257551 10/1990" should read 2-257551 10/1990--;

"1031332 2/1989" should read --1-031332 2/1989--;

"03048889 1/1991" should read --03-048889 1/1991--;

"04204993A 7/1992" should read --04-204993A 7/1992--;

"02273720 8/1990" should read --02-273720 8/1990--;

"02272490 7/1990" should read --02-272490 7/1990--;

"0 707 301 A1 4/1976" should read --0 707 301 A1 4/1996--; and

Other Publications after ""Physical":

"Emisssion" should read -- Emission -- and

"Molybedium" should read --Molybdenum--.

SHEET 5:

Figure 5, "LIMINANCE" should read -- LUMINANCE--.

SHEET 6:

Figure 6, "REGURATOR" should read -- REGULATOR-- and "RAGURATOR" should read -- REGULATOR--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

10 31 coo



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 7:

Figure 7, REGURATOR" should read --REGULATOR-- and "RAGURATOR" should read --REGULATOR--.

COLUMN 1:

Line 2, "DISPLAY" should read -- DISPLAY ¶TECHNICAL FIELD--.

COLUMN 2:

Line 8, "denium" should read --denum--.

COLUMN 3:

Line 12, "Microele-ctronics" should read -- Microelectronics--.

COLUMN 4:

Line 21, "3kv" should read --3kV--.

COLUMN 6:

Line 57, "while" should read --while an image--.

COLUMN 15:

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

" 3 1 2000



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "step s47." should read --step S47.--.

COLUMN 28:

Line 54, "show" should read --shows--.

COLUMN 33:

Line 9, "take" should read --taken--.

COLUMN 34:

Line 1, "for" should read --that--;

Line 19, "character graphic" should read --character-graphic--; and

Line 22, "character graphic" should read --character-graphic--.

COLUMN 36:

Line 37, "source; an" should read --source; ¶ an--; and

Line 65, "source; an" should read --source; ¶ an--.

COLUMN 37:

Line 18, "comprising" should read --comprises--;

Line 27, "source; an" should read --source; ¶ an--;

Line 47, "comprising" should read --comprises--; and

Line 51, "connect" should read --connected--.

Line 56, "source; an" should read --source; ¶ an--;

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

TOURS PROTECTION



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,972,741 B1

DATED

December 6, 2005

INVENTOR(S) :

AOJI ISONO ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 14, "shutdown" should read --shutdown,--;

Line 19, "comprising" should read --comprises--;

Line 28, "source; an" should read --source; ¶ an--;

Line 41, "battery;" should read --battery; and--; and

Line 50, "source-comprising" should read --source comprises--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,972,741 B1</u>

No. of add'l. copies @ 30¢ per page

了的信息

